

Diesel Agencies Limited

P O Box 38-100, Petone, New Zealand

Phone:(4)729 308 Fax:(4)686611

7th December 1988

The Manager
DE-BUG Filters Limited
Petone

Attention Mrs Forrest


We have recently completed fitting fifteen of your De-Bug Fuel Treatment Units to the 26kva diesel generator sets owned by two major shipping companies. These generator sets are used to power refrigerated containers while on the railway waggons moving them to the ports and the requirement for a high level of reliability is paramount.

It is now over a year since the first De-Bug was fitted and we have not encountered any of our usual batch of problems with generator sets having a De-Bug installed in the fuel system. Much better than this however, when the annual service checks are carried out filter screens and cartridges are in such a clean condition with none of the usual sediment in the filter chamber that we are considering extending the service period. Vibration levels remain low for the full in service period, no doubt due to the increased reliability of the fuel injection equipment.

As requested, over this last year we have drawn off several fuel samples for visual inspection and find the gas oil in the tanks from the units fitted with a De-Bug to be crystal clear, as against the dirtier coloured fuel from untreated sets.

This hard evidence has proved very beneficial to us because two other major operators have now placed orders to fit De-Bugs on similar diesel generator units. We look forward to placing another order with your company in the near future.

Yours faithfully



Tony Johnston
Director